

ABSTRACT

In order to provide a superconducting wire that has a high critical current value, has no defects such as bulges, and has high mechanical strength, an oxide superconducting material (1) is covered, and ceramic particles or fibers (3) are buried in the surface of a covering (2) made of metal

FIG. 2